


Land Subsidence in the Picacho Sub-Basin, Pinal County
Based on ADWR EnviSat Time-Series InSAR Data
Time Period of Analysis: 0.8 Years 04/18/2007 To 02/27/2008

© ESA 2007 - 2008

04/18/2007 To 02/27/2008

Subsidence



Subsidence Feature


Hardrock

CAP Canal

Arizona Highways and Interstates

Interstate
US
State
Roads
Railway

1:335,099



Decorelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).